



**SPORT PERFROMER SRL**

**NEW PRODUCTS 2024**

**HL SOLID SKIWAX**

**FLUOR FREE**



<p><b>Art. HL4-22 22 gr</b>  <b>Art. HL4-5 5 gr</b>          AIR HUMIDITY 40 – 100%          SNOW TEMP. 0°/-8°C          AIR TEMP +3°/-11°C</p>	<p><b>Art. HL5-22 22 gr</b>  <b>Art. HL5-5 5 gr</b>          AIR HUMIDITY 40 – 100%          SNOW TEMP. -8°/-15°C          AIR TEMP -5°/-18°C</p>	<p><b>Art. HL6-22 22 gr</b>  <b>Art. HL6-5 5 gr</b>          AIR HUMIDITY 40 – 100%          SNOW TEMP. -10°/-20°C          AIR TEMP -7°/-23°C</p>
---	---	--

**HL4, HL5, HL6 Solid skiwax**, designed for stand-alone application. No fluorine, no solvents.

Their application over a base of S30 is recommended for long distances skiing or with very abrasive snow.

**SUPERGLIDE LIQUID**

**90ml**

**FLUOR FREE**




<p><b>Art.0088YL 90ml</b>          AIR HUMIDITY          50 – 100%          SNOW TEMP. 0°/-1°C          AIR TEMP +5°/-4°C</p>	<p><b>Art.0088RL 90ml</b>          AIR HUMIDITY          50 – 100%          SNOW TEMP. -2°/-10°C          AIR TEMP 0°/-13°C</p>	<p><b>Art.0088PL 90ml</b>          AIR HUMIDITY          50 – 100%          SNOW TEMP. -2°/-8°C          AIR TEMP +1°/-10°C  <b>FOR NEW SNOW</b></p>	<p><b>Art.0088GL 90ml</b>          AIR HUMIDITY          50 – 100%          SNOW TEMP. -10°/-20°C          AIR TEMP -7°/-24°C</p>
---	---	--	---

**Ski wax** suitable for transformed snow/new snow and air humidity 50-100%. Perfect combination of smoothness and resistance with ease of application. **Instructions for use:** distribute the product all over the ski botton, leave to dry for 5/6 minutes and polish with a soft cloth.

## S20 ANTISTATIC SOLID SKIWAX

FLUOR FREE



SNOW TEMP. -5°/-20° AIR TEMP -1°/-24°C AIR HUMIDITY: 10%/100%


<b>180 gr</b>	<b>2X250 gr</b>	<b>2X500 gr</b>
<b>ART.0720-18</b>	<b>ART. 0720-2X25</b>	<b>ART. 0720-2X50</b>

This product is particularly suited for conditions of low air humidity (below 50%) and for dry, wind-blown and cold snow.

IRON : 130°/135°C

## S30 HARDENER solid SKIWAX

FLUOR FREE



SNOW TEMP. -15°/-30°C AIR TEMP -11°/-34°C AIR HUMIDITY: 10%/100%

<b>180 gr</b>	<b>2X250 gr</b>	<b>2X500 gr</b>
<b>ART.0730-18</b>	<b>ART. 0730-2X25</b>	<b>ART. 0730-2X50</b>

Ideal for artificial, cold and abrasive snow. Applied to ski-edges, S30 HARDENER avoids wearing down the base.

IRON: 130°/135°C